

SUPPLEMENTAL TYPE CERTIFICATE

10052197

This Supplemental Type Certificate is issued by EASA, acting in accordance with Regulation (EC) No. 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation and in accordance with Commission Regulation (EU) No. 748/2012 to

TESTORI AERO SUPPLY S.R.L.

VIA DON G. BRAMBILLA 19 23844 SIRONE (LC) ITALY

and certifies that the change in the type design for the product listed below with the limitations and conditions specified meets the applicable Type Certification Basis and environmental protection requirements when operated within the conditions and limitations specified below:

Original Type Certificate Number: EASA.IM.A.120

Type Certificate Holder: THE BOEING COMPANY

Type Design - Model: 737-600

737-700 737-800 737-900 737-900ER

Description of Design Change:

Flight Attendant Seat Cushion Replacement for Boeing 737 NG series

EASA Certification Basis:

None

Associated Technical Documentation:

Component Maintenance Manual and IPC TAS-STC-B737NG-FA-CMM-01 or later revisions of the above listed documents approved by EASA Master Document List TAS-STC-B737NG-FA-MDL-01 Rev. 03 Master Drawing List TAS-STC-B737NG-FA-MWL-01 Rev. 00

See Continuation Sheet(s)

For the European Aviation Safety Agency,

Date of issue: 09 February 2015

Alain LEROY
Head of Large Aeroplanes Department

Note:

The following numbers are listed on the certificate: EASA current Project Number: 0010034850-001

SUPPLEMENTAL TYPE CERTIFICATE - 10052197 - TESTORI AERO SUPPLY S.R.L.



Limitations/Conditions:

Prior to installation of this design change it must be determined that the interrelationship between this change and any other previously installed design change will introduce no adverse effect upon the airworthiness of the product.

- end -